



Attorney Docket No. 1466.1039

co/c

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Takashi SHIZAKI, et al.

Application No.: 09/885,001

ATTENTION

Confirmation No.: 3545

CERTIFICATE OF CORRECTION

Filed: June 21, 2001

BRANCH

U.S. Patent No.: 7,116,288

Issued: October 3, 2006

For: DRIVING METHOD OF PLASMA DISPLAY PANEL AND DISPLAY DEVICE

**REQUEST FOR CERTIFICATE OF CORRECTION**

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: Dec. 19, 2006

By: H. J. Staas  
H. J. Staas  
Registration No. 22,010

1201 New York Ave, N.W., 7th Floor  
Washington, D.C. 20005  
Telephone: (202) 434-1500  
Facsimile: (202) 434-1501

*Certificate  
DEC 21 2006  
of Correction*

*DEC 26 2006*

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.  
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO : 7,116,288

DATED : October 3, 2006

INVENTOR(S) : Takashi SHIIZAKI, et al.

First page, Column 2 (Abstract), Line 1, after "having" delete "a".

MAILING ADDRESS OF SENDER:  
STAAS & HALSEY LLP  
1201 New York Ave., N.W.  
7th Floor  
Washington, DC 20005

PATENT NO. 7,116,288

No. of add'l copies  
@ 50¢ per page

⇒

DEC 26 2006